

# Vipros 367 Queen Machine Programming Limits



7025 Firestone Blvd.  
Buena Park, CA 90621  
Phone: 714-739-2111  
Fax: 714-739-4099  
Email [Info@amada.com](mailto:Info@amada.com)

# Table of Contents

Programmable Travel Limits .....3

Programmable Feed Rates .....4

    Table Speed Punching Mode.....4

    Table Speed Interpolation Mode.....4

    Turret Rotation Speed.....4

    Auto Index Rotation Speed .....4

    Punching Speed.....4

Punch Confirmation Area / Punching Dead Zone.....5

    Definitions .....5

    Punch Confirmation Area .....6

    Punching Dead Zone. ....7


Material Clamp Locations.....8

Reposition Holddown Locations .....9

Work Chute / Trap Door (ball transfer table only) .....10

58 Station Turret .....11

# Programmable Travel Limits



Origin Statement		X-axis Movable Distance	Y-axis Programmable Distance By Track Numbers		
X-axis Origin	Y-axis Origin		Inner Track 100 Stations	Center Track 200 Stations	Outer Track 300 Stations
72.000"	60.000"	-.394" to 72.441"	1.181" to 61.614"	-.394" to 60.040"	-1.969" to 58.465"

## Programmable Feed Rates

### Table Speed Punching Mode

F1 = X 2,559. IPM Y 1,968. IPM

F2 = X 1,919. IPM Y 1,476. IPM

F3 = X 1,279. IPM Y 984. IPM

F4 = X 639. IPM Y 492. IPM

### Table Speed Interpolation Mode

G00 max. = X 2,559. IPM Y 1,968. IPM

G01 max. = 300. IPM

G02 max. = 300. IPM

G03 max. = 300. IPM

### Turret Rotation Speed

30 RPM

### Auto Index Rotation Speed

60 RPM

### Punching Speed


	Pitch	Stroke	Stroke Rate
Stroke Rate (X/Y)	0.079"	0.118"	520/420
	0.079"	0.236"	360/360
	0.315"	0.315"	275/275
	1.000"	0.315"	275/240

## Punch Confirmation Area / Punching Dead Zone.


### Definitions

- Confirmation Zone = An area that when the confirmation switch is in the on position or it is the first run of the part program the operator must confirm the punch by pressing the confirmation pushbutton.
- Punch Dead Zone = An area that when the confirmation switch is in the on position or it is the first run of the part program the operator must confirm the punch by pressing the confirmation pushbutton. Punching in this area with standard tools may damage the material, material clamp, tool, other machine components and may cause operator injury.
- Y-Overtravel Zone = An area that exceeds the travel limits of the machine.

# Punch Confirmation Area




# Punching Dead Zone.



Punching Dead Zones		
"The punch will contact the material clamp when programmed to punch in the area described by the following calculations".		
X-axis	To the left of the clamp	Clamp position -1.575" - a - d/2
	To the Right of the clamp	Clamp position +1.575" + a + b + d/2
Y-axis	.394" + a + d/2	


b=	.500"		
a=	.500"		
d=	Station Size	A	1.020"
		B	1.883"
		C	3.500"
		D	4.938"
		E	6.250"

# Material Clamp Locations






# Reposition Holddown Locations




# Work Chute / Trap Door (ball transfer table only)



# 58 Station Turret

PEGA 345, PEGA 345 King, PEGA 357, PEGA 367  
 COMA 555, COMA 557, COMA 567, COMA 588  
 VIPROS 345, VIPROS 357, VIPROS 367  
 VIPROS 357 Queen, VIPROS 367 Queen



MAXIMUM SIZE ROUND		NUMBER OF STATIONS ( KEYED )	
A	1/2" ( 12.7mm )	36 ( 12 )	
B	1 1/4" ( 31.7mm )	12 ( 12 )	
C	2" ( 50.8mm )	4 ( 4 )	
D	3 1/2" ( 88.9mm )	2 ( 2 )	
E	4 1/2" ( 114.3mm )	2 ( 2 )	
AUTO INDEX	B	1 1/4" ( 31.7mm )	2 ( 2 )